WICHITA FIELD EVIDENCE / CONTROLLED ACCESS TEST

Roof Repairability Analysis

Follow a real access test at a box vent. Nearby courses, seals and fastening access remain part of the construction question.




00:20 / Tool placement



01:40 / Adjacent course lifted



03:20 / Condition during the test



04:40 / Test-area overview

A repair has a ripple effect.

These stills preserve specific points in the original recording. They document access around the vent and the manipulation of neighboring courses; they do not, by themselves, establish the necessary extent of replacement on another roof.


Source: Crown Wichita inspection, July 31, 2026; original video V4, total duration 4:55.60. Still-frame timestamps retained.

Request my Roof Repairability Analysis

ACTUAL REPORT EXCERPT / ORIGINAL P. 7

The documented takeaway.

Read the original Controlled Access Test page with its source photo IDs and stated construction implications.



Source: Crown Current Roof Condition & Repairability Documentation, p. 7. Public excerpt; customer details omitted.