
PROPERTY REPORT

Your roof. Your solar. Your next step.



ONE PROPERTY. ONE CONTROLLED PLAN.

01 Document roof + solar condition.

02 Verify permits + installer support.

03 Complete the claim evidence file.

04 Coordinate safe removal and reset.

AUG 24
2026 inspection

274
Photos reported in archive

50 / 100
Provisional readiness

HOMEOWNER EXAMPLE

Kansas City, Missouri | Property address withheld

Installer coordination edition | Contractor condition, causation and next-step review. Field investigation pending.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

01 / PROPERTY SUMMARY

The record for this property

Inspection	August 24, 2026; source describes 274 timestamped originals. This edition preserves the 26 selected evidence photographs.
Roof + PV	Architectural asphalt shingles, multiple roof planes, roof-mounted photovoltaic arrays and marked roof/collateral conditions.
Storm window	August 19, 2026; regional NWS hail reports cited in the inspection report. Parcel-specific hail size remains unverified.
Installation record	[permit ID withheld] | SUN SOLAR LLC | issued August 6, 2020; completed/closed September 2, 2020. [S3]
System identity	Module/inverter models, wattages, exact capacity, monitoring access and warranty terms remain open.
Installer continuity	Public records support ongoing business and an advertised service channel. Service responsibility for this particular system is unconfirmed. [S5-S7]

RECOMMENDED NEXT STEP

Develop a coordinated roofing/PV scope, obtain the pre-removal production baseline, and confirm installer service responsibility before choosing equipment changes.

02 / CLAIM READINESS

50 / 100 — evidence in progress

Provisional document-completeness score | New rubric for this revision

Evidence category	Points	Basis for points
Property + inspection identity	10 / 10	Named property and dated inspection.
Photo traceability	15 / 20	26 selected photos with filenames; full 274-file archive not reviewed here.
Storm evidence	10 / 15	Regional event described; parcel exposure/cause not established.
Causation + repairability	5 / 20	Marked locations documented; repair tests and final scope not supplied.
PV diagnosis + baseline	0 / 15	No inverter label, diagnostic export or production baseline supplied.
Permit + installer identity	10 / 10	Exact property permit independently retrieved from city dataset.
Claim file + prior history	0 / 10	Insurer, claim number, prior decisions and policy file not supplied.

Method: sum the points above (maximum 100). Full points require the listed evidence; partial points reflect incomplete documentation. Proposed bands: 0-39 initial record; 40-69 evidence in progress; 70-89 review-ready; 90-100 documented file. All critical open items still require review.

WHAT THIS SCORE MEANS

A transparent checklist of the documentation available for this revision. It is not a probability of damage or insurance payment, a carrier standard, or the weather-exposure score used in source report. No human field verification or claim approval is implied.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

03 / PERMIT HISTORY

The solar installation record

Independently retrieved November 11, 2026 | KCMO official dataset [S3-S4]

Permit	[permit ID withheld]
Property match	[property address withheld] | Kansas City, MO 64116 | PIN [ID withheld]
Contractor	SUN SOLAR LLC
Work recorded	Roof Mounted Solar Installation per plans reviewed for code compliance.
Application / issue	August 5, 2020 / August 6, 2020
Completed / status	September 2, 2020 / Closed
Reported project cost	$6,975 (permit-reported value; not a replacement estimate)

INSTALLER PERMIT ACTIVITY

139 records match the exact contractor name SUN SOLAR LLC in this city dataset. Issue dates span August 6, 2020-March 5, 2025. The latest listed permit is CPER-2025-00811, closed April 8, 2025. Similar names such as Artisun Solar are excluded.

Dataset freshness: the retrieved city metadata reports the last data update as May 9, 2025. These historical records do not establish 2026 permitting activity, current licensing, utility permission to operate, or ongoing maintenance. The exact address query returned the one installation record above.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

04 / INSTALLER CONTINUITY

Is Sun Solar still servicing systems?

Public-source review as of November 11, 2026

OPERATING BUSINESS — SUPPORTED BY PUBLIC EVIDENCE

Sun Solar's current contact page lists its main and service lines and offices serving Kansas City. Its BBB profile names Sun Solar LLC / Missouri Sun Solar, LLC, with matching Springfield contact details. These support continued operations; a state good-standing certificate was not obtained. [S5-S6]

SERVICE CHANNEL — PUBLICLY ADVERTISED

Service line: 417-233-5720. Main line: 417-413-1786. The company's own service description says its team handles design, permitting, installation and servicing. This verifies an advertised service channel, not response time or acceptance of this address. [S5, S7]

THIS SYSTEM — SERVICE RESPONSIBILITY UNCONFIRMED

No current owner service agreement, support ticket, maintenance invoice, portal ownership record or installer acknowledgement was found in the reviewed materials. An installer still operating does not prove it is maintaining this system.

To close this item: obtain written confirmation for [property address withheld] and permit [permit ID withheld]; identify the service/warranty holder; confirm monitoring access, open faults, warranty transfer and detach/reset support. Attach the dated response to this file.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / SPATIAL IDENTITY

One parcel. A dated source chain.

Historical orthophotography and satellite imagery | Research November 11, 2026

County parcel match	Clay County public parcel layer: identifiers and street address withheld. Mapped area 0.2947 acres. County property IDs differ from city permit IDs.
Map center	Exact coordinates withheld (WGS84). Position selected within the matched parcel, centered on the roof rather than the street-interpolated address point.
Viewing geometry	Web Mercator tiles at level 19, common crop approximately 69.45 m wide at this latitude; north is up. Yellow lines are the county parcel overlay, not a survey or roof-edge measurement.
Image resolution	Display sampling approximately 0.2315 m/pixel. Native source resolution varies from about 0.15 to 0.50 m; zooming does not add shingle detail. Source positional accuracy is approximately 0.73-5 m.
Date rule	Capture date (SRC_DATE / SRC_DATE2) is distinct from the Wayback map-release date. Repeated yearly nodes may reuse the same source image and are expressly marked.
Evidence retained	Exact tile and metadata query URLs, provider, native resolution, archive item, decoded-image hash and parcel geometry are retained in the imagery register and source bundle.

Sources: Clay County parcel service; Esri World Imagery Wayback configuration and metadata. Attribution follows each source: Microsoft / DigitalGlobe / Maxar / Vantor or MO911 Service Board / MDC, as applicable. No image was generated or filled in to create a missing historical observation.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / ANNUAL TIMELINE

2012-2014: the historical record

Each bullet is a calendar-year checkpoint; the source capture date below controls.



2012

Capture: 2012-02-19 | Microsoft
Native 0.3 m | map release 2014-12-30
Roof and house form visible; no obvious PV array. Shingle installation date is not resolved.



2013

Capture: 2012-02-19 | Microsoft
Native 0.3 m | map release 2014-12-30
No distinct 2013 capture retrieved. The 2012 image is repeated for continuity.



2014

Capture: 2012-02-19 | Microsoft
Native 0.3 m | map release 2014-12-30
No distinct 2014 capture retrieved. This map release still uses the February 2012 image.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / ANNUAL TIMELINE

2015-2017: the historical record

Each bullet is a calendar-year checkpoint; the source capture date below controls.



2015

Capture: 2012-02-19 | Microsoft
Native 0.3 m | map release 2015-12-16
No distinct 2015 capture retrieved. The source remains February 2012.



2016

Capture: 2012-02-19 | Microsoft
Native 0.3 m | map release 2016-12-20
No distinct 2016 capture retrieved. The source remains February 2012.



2017

Capture: 2017-06-15 | DigitalGlobe
Native 0.5 m | map release 2018-12-14
Leaf-on cover and lower clarity limit roof comparison; no unambiguous reroof event is resolved.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / ANNUAL TIMELINE

2018-2020: the historical record

Each bullet is a calendar-year checkpoint; the source capture date below controls.



2018

Capture: 2017-06-15 | DigitalGlobe
Native 0.5 m | map release 2018-12-14
No separate 2018 capture in the reviewed year-end release; June 2017 is repeated.



2019

Capture: 2017-06-15 | DigitalGlobe
Native 0.5 m | map release 2019-12-12
No separate 2019 capture in the reviewed release; June 2017 is repeated.



2020

Capture: 2020-05-02 | Maxar
Native 0.5 m | map release 2020-12-16
Pre-solar view: no clearly resolved array. Haze and canopy limit roof-surface interpretation.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / ANNUAL TIMELINE

2021-2023: the historical record

Each bullet is a calendar-year checkpoint; the source capture date below controls.



2021

Capture: 2021-09-09 | Maxar
Native 0.31 m | map release 2022-12-14
Post-solar view: dark module blocks appear on the roof. A roof replacement is not independently established.



2022

Capture: 2022-11-20 | Maxar
Native 0.31 m | map release 2023-12-07
Array blocks remain visible. Exposed roof tone varies with acquisition conditions.



2023

Capture: 2023-10-08 | Maxar
Native 0.31 m | map release 2024-12-12
Leaf-on vegetation obscures part of the roof. No clear reroofing sequence is captured.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / ANNUAL TIMELINE

2024-2026: the historical record

Each bullet is a calendar-year checkpoint; the source capture date below controls.



2024

Capture: 2024-02-13 | MO911ServiceBoard,MDC
Native 0.152 m | map release 2026-10-29
Two captures exist: Feb 13 county aerial and Nov 10 satellite. County aerial shown for detail; later satellite retained.



2025

Capture: 2024-11-10 | Vantor
Native 0.34 m | map release 2025-12-18
No new 2025 acquisition used here; November 2024 is repeated from the 2025 release.



2026

Capture: 2024-02-13 | MO911ServiceBoard,MDC
Native 0.152 m | map release 2026-10-29
Latest reviewed 2026 release uses February 2024 county aerial; it is not a new 2026 roof photograph.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / COMPARATIVE PLATE

Before solar. After solar.

Compare roof form and array presence; material continuity remains an open question.



2012-02-19 | Microsoft



2024-02-13 | Clay County aerial

Observed: the roof form is present in the 2012 capture; later images show a roof-mounted PV array. Lighting, season, canopy, view angle and source processing differ. Similar roof outlines or a changed color do not establish whether the same shingle covering remains.

What would support a replacement window: a clear before/after resurfacing sequence, exposed decking/tear-off or documented materials delivery, independently tied to roof invoices, a reroofing permit or installer pre-install assessment. Those corroborating records were not found here.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / AGE INFERENCE

The supported answer—and the uncertainty

A two-year roof replacement window cannot be established from the reviewed images alone.

Strong finding	Solar is not clearly resolved in the May 2, 2020 capture and appears by September 9, 2021. Permit [permit ID withheld] was closed September 2, 2020, narrowing the documented solar-work chronology.
Roof finding	No unequivocal reroofing event was identified in the available frames. Roof appearance and footprint are not enough to prove current covering continuity from 2012 or a reroof in 2020.
Actual roof age	UNVERIFIED. No point estimate or +/-2-year installation interval is assigned. The record supports hypotheses to test, not a definitive roof installation date.
Conditional older-roof scenario	IF the current covering was already installed on February 19, 2012 and was never replaced, it would be at least 14.50 years old on the candidate August 19, 2026 event date. Continuity is unproven.
Conditional solar-era scenario	IF independent evidence proves roof installation on August 6, 2020, it would be about 6.04 years old at that candidate event. The solar permit alone does not prove this scenario.
Next verification	Obtain roof invoice/warranty and Sun Solar's pre-install roof survey; ask the owner about reroofing and prior detach/reset. Use a qualified field review to document material/repair history.

Depreciation uses a supported installation date and valuation/loss date, not a map-release year. August 19, 2026 is a candidate event from the source report, not a proven date of loss or a carrier-accepted valuation date.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / ROOFQUOTE PRO ATTEMPT

The actual estimator excerpt

Correct property located | Medium slope suggested by the estimator | Quote not issued



Verified screen: Crown's RoofQuote PRO / Roofle widget resolves the subject Kansas City property
USA and draws the Main Roof outline. The suggested slope category is Medium; no numeric pitch has been field-verified.

Outstanding: area, squares, waste, billable quantity, Good-option product and price remain unavailable because the public flow requires a contact/verification step with reCAPTCHA before pricing. No quote was issued and no measurements or price were fabricated. The older Red Oak Lane quotes belong to other properties and were not used.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / QUANTITY RECONCILIATION

Audit size, waste and the Good price

Complete these fields from the actual proposal before using a property-specific cost basis.

Footprint A_h	Horizontal projected roof polygon area in sq ft; not lot area. Compare map outline with site conditions.
Pitch / plane area	For a simple plane: factor = sqrt(1 + (rise/12)^2). Surface area = footprint x factor. For multiple pitches, sum each plane separately.
Waste w	Use actual product/layout-based waste. Order area = surface area x (1+w). Confirm whether the source quantity already includes waste before multiplying.
Squares + bundles	Squares = order sq ft / 100. For 3-bundle-per-square products, round package counts upward to whole bundles; verify each selected product's actual coverage.
Good option	Use the actual base laminated-asphalt product, selected package, scope, exclusions and written range/fixed price. A 30-year depreciation assumption is not proof of a product's warranty or actual service life.
Roof / solar split	Separate roofing from PV detach/reset, diagnostics, storage, remount/commissioning and upgrades. Do not assume those costs are included or depreciated on the same basis.
Current values	This property's measured area, numeric pitch, waste %, Good-option price and proposal ID are pending. The spreadsheet quantity cells remain blank rather than borrowing figures from another roof.

Retail estimate date and covered loss-date valuation are distinct. A contractor's retail price does not automatically equal the insurer's accepted scope or replacement-cost amount.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / SETTLEMENT MATHEMATICS

Depreciation, deductible and recovery

User assumptions: $5,000 deductible; 30-year laminated-asphalt life for this scenario model.

INPUTS AND DEFINITIONS

R = accepted comparable replacement scope; B = the part eligible for depreciation; A = supported age at valuation; L = 30 years; D = $5,000. In the worked example only, R = B = $20,000. That amount is illustrative, not a RoofQuote PRO price.

Fraction f	f = min(max(A / L, 0), 1)
Depreciation delta	delta = min(B,R) x f
Gross ACV	ACV_gross = max(0, R - delta)
Initial ACV net	I = max(0, R - delta - D)
Completed eligible RCV	F = max(0, R - D), assuming full replacement of the accepted scope and satisfaction of recovery conditions.
Potential later recovery	H = max(0, F - I)
Owner funding	RCV owner = R - F; ACV-only owner = R - I; extra ACV-only burden = H.
Do not double-deduct	The deductible appears once. When depreciation pushes ACV below the deductible, recovery lost is capped by the net RCV benefit. Do not add depreciation and the deductible twice.

Actual depreciation methods, depreciable labor/items, limits, taxes, code items, excluded work and recovery requirements depend on the claim and applicable terms. This is contractor scenario arithmetic; the insurer determines coverage and payment.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / WORKED DOLLAR EXAMPLE

If the roof were 15 years old

Illustrative R = $20,000 | D = $5,000 | L = 30 years | A = 15 years

Depreciation fraction	15 / 30 = 0.50 = 50%
Depreciation dollars	$20,000 x 0.50 = $10,000
Gross ACV	$20,000 - $10,000 = $10,000
Initial net payment	$10,000 - $5,000 deductible = $5,000
Eligible final RCV payment	$20,000 - $5,000 deductible = $15,000
Potential later depreciation recovery	$15,000 - $5,000 initial = $10,000
Owner under eligible completed RCV	$20,000 - $15,000 = $5,000
Owner under ACV-only	$20,000 - $5,000 = $15,000
Extra amount left unrecovered	$15,000 owner ACV - $5,000 owner RCV = $10,000

THE FUNDING DIFFERENCE

In this scenario the homeowner supplies $15,000 under ACV-only versus $5,000 after eligible RCV recovery. The $10,000 difference is the foregone recovery—not an automatic benefit and not the entire replacement cost. This roof's actual age and policy terms remain unverified.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK


INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / AGE SENSITIVITY

The uncertainty changes the dollars

Same illustrative $20,000 scope and $5,000 deductible; no actual roof age is selected.



Age	Dep %	Dep dollars	ACV net	Owner ACV	Extra vs RCV
6	20.00%	$4,000.00	$11,000.00	$9,000.00	$4,000.00
10	33.33%	$6,666.67	$8,333.33	$11,666.67	$6,666.67
12	40.00%	$8,000.00	$7,000.00	$13,000.00	$8,000.00
14.5	48.33%	$9,666.67	$5,333.33	$14,666.67	$9,666.67
15	50.00%	$10,000.00	$5,000.00	$15,000.00	$10,000.00
20	66.67%	$13,333.33	$1,666.67	$18,333.33	$13,333.33
25	83.33%	$16,666.67	$0.00	$20,000.00	$15,000.00
30	100.00%	$20,000.00	$0.00	$20,000.00	$15,000.00

Owner RCV remains $5,000 in these examples after full eligible recovery. At higher ages, the initial ACV payment reaches $0; lost recovery is capped at $15,000 rather than increasing without limit.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / CROWN NETWORK TRIGGERS

When the investigation is activated

Proposed operational rules from Crown's program brief—not proof of damage or coverage.

System age / partner route	Preferred-partner systems at least 10 years old are eligible for inverter efficiency/production diagnostics. Confirm commissioning and inverter replacement dates; an old system may have a newer inverter. Eligibility does not prove a defect.
Performance route	Crown service/network monitoring flags a persistent weather-adjusted deficit or operational fault under the rules on the next page. Investigate equipment, communications and operating conditions.
Hail route	A credible at-property report or storm footprint consistent with hail at least 1.00 inch activates the property condition/causation investigation queue. Regional reports are triage evidence and still require property correlation.
Wind route	Wind above 80 mph sustained for at least 5 minutes, or recurrent qualifying episodes over several hours, activates the queue when supported by duration-capable records. A single 80-mph gust is not a five-minute sustained measurement.
Public source controls	Retain location/time, station/report type, gust vs mean, measurement vs estimate, duration, swath and uncertainty. NWS/NOAA, quality-controlled station records and other traceable third-party evidence support the chronology.
Property today	2020 solar permit indicates about six years of service if original equipment remains. The 10-year pathway is not established. Regional hail cited by the source report warrants correlation; qualifying sustained wind at this parcel has not been verified.

Activation means a documented investigation and contact/access coordination, not an automatic insurance claim, policy outcome, intrusive test authorization or attribution of a loss date. Crown reports both supporting and conflicting evidence.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / 24-HOUR MONITORING

A measurable diagnostic threshold

Proposed Crown screening rule | Commission and validate it for each system before activation

PRIMARY TRIGGER: 20% DEFICIT FOR 3 ELIGIBLE DAYS

ER = measured AC kWh / expected AC kWh for the same interval. Deficit = 1 - ER. Flag a diagnostic when deficit is at least 20% (ER <= 0.80) on three consecutive eligible production days. This is an operational threshold selected for review, not a manufacturer warranty criterion or an insurance-loss probability.

Baseline	Use verified equipment/array geometry and a weather-adjusted model calibrated with at least 30 verified-good operating days. Retain model version, age/degradation assumption, shading, temperature, outages and curtailment exclusions.
Eligible day	At least 95% daylight telemetry completeness; representative daily plane-of-array irradiation at least 3.0 kWh/m2; grid available; expected energy positive. Missing reliable weather/production data creates a data-quality task, not a proven loss.
Other operational alerts	Zero production for two continuous daylight hours with valid irradiance above 200 W/m2, grid available and no planned shutdown: prompt diagnostic triage. Lost telemetry for 24 hours: communications/access check first. Manufacturer fault alarms are handled under the relevant safety/service procedure.
Example only	Expected 30 kWh/day; measured 23, 22 and 24 kWh = deficits 23.3%, 26.7% and 20.0%. With eligible data on all three consecutive days, the proposed trigger is met. This is not Property production data.
Included annual diagnostic	Crown service includes 24/7 automated monitoring where supported and one free diagnostic test per service year. The included annual review can be brought forward by a qualifying trigger; additional work and ongoing service terms are confirmed separately.

Method basis: DOE/NREL compares aligned measured/model production, availability and environmental inputs. Crown's 20% / 3-day and data-quality rules are proposed operational choices, not thresholds prescribed by DOE/NREL.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / DIAGNOSTIC SCOPE

Identify it. Test it. Explain the result.

Construction inspection plus qualified solar diagnostics, with a written record and owner walkthrough

Module technology	Read manufacturer/model/serial labels and datasheets; distinguish monocrystalline, polycrystalline or other technology. Record count, nameplate watts, degradation/warranty terms and visible condition. Do not infer the exact module from appearance.
Manufacturer tiers	If a tier claim is relevant, record the dated classification and source. BNEF Tier 1 concerns manufacturer bankability/financed use, not a product-quality certification. Tier 2/3 labels are not used here as standardized engineering grades.
Inverter architecture	Identify string inverter, optimizer-equipped string, microinverter and/or hybrid/storage arrangement; log replacements, serials, faults, rated input/output and monitoring topology.
Efficiency / production testing	Qualified personnel measure simultaneous AC output and DC input under documented conditions: inverter efficiency = AC output / DC input. Production analysis uses kWh and weather normalization; it is not the same metric as instantaneous inverter efficiency.
Mounting + roof interfaces	Identify rails/rail-less hardware, clamps, flashing/feet, fasteners, attachment spacing, seal/roof interfaces, corrosion, cable protection and bonding. Compare with the actual equipment instructions and accessible construction conditions.
Warranty	Some string inverters, including products advertised by SolarEdge, carry a 12-year standard warranty with model-dependent extensions. Exact brand, serial-specific start date, extensions, transfer/labor terms and replacement history control. A 10-year diagnostic is preventive; it does not establish warranty expiry.

The included annual diagnostic covers the applicable equipment/roof-interface review, monitoring/production assessment, owner education and written contractor findings. Testing follows qualified access and applicable instrument/manufacturer procedures; a specialist referral is identified when the question exceeds the reviewer's qualifications.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / OWNER CLARITY

The owner should understand the system.

Complete this walkthrough during the investigation and Crown's included annual diagnostic review.

Access + controls	Confirm the owner can sign into the monitoring app, reset access, identify system/installer contacts and view production/alerts. Explain what is monitored, update intervals, data outages and alert escalation.
Energy vocabulary	kW is instantaneous power; kWh is energy over time. Separate solar generation, household use, grid imports, grid exports and billing-period netting. A production app alone may not measure whole-home consumption.
Net metering	Identify the actual utility, jurisdiction, interconnection/PTO, meter and tariff. Review exported-energy credits, time-of-use periods, fixed charges, carry-forward/expiration and any true-up. Export credits need not equal the retail import rate or a cash payment.
Loan / lease / PPA	Identify the agreement type, owner/lender/servicer, payment amount and due date, APR/term, outstanding balance, escalators, any deferred principal/balloon or tax-credit-related payment assumption, liens, transfer and payoff rules. Verify from the agreement; do not promise savings or tax outcomes.
Two separate obligations	A loan or lease payment is separate from utility charges and credits. Monitoring, a service change or a claim does not automatically change the financing agreement, equipment ownership or utility tariff.
Record the outcome	Provide the owner a plain-language summary: what they own, who services it, how to access monitoring, what they pay, what utility credits mean, and the next action for any unanswered question. Record source documents and the owner's walkthrough acknowledgement.

For illustration of tariff variability, Evergy's published time-based options describe surplus credit at average production cost and allocation within the relevant time period. Verify this home's actual utility and tariff before applying those rules.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / EXPERT REVIEW + SERVICE ELECTION

Who reviewed it—and who services it?

Complete after the actual investigation | Service choice and provider acceptance are separate records

FIELD REVIEW / EXPERT SIGN-OFF

REVIEWER NAME

RELEVANT QUALIFICATIONS

INVESTIGATION / REVIEW DATE

REVIEWER SIGN-OFF

Reviewer signs only for work actually performed within their documented expertise. The current desk review does not supply a field expert certification.

ONGOING SOLAR SERVICE

- Continue original service agreement
- Select Crown service for follow-up
- Select another preferred solar partner

FIRM HANDLING THIS CLIENT

SERVICE CONTACT / CASE NUMBER

Confirm the original agreement's status and obtain the selected provider's acceptance/effective date. A checked box alone does not transfer an existing agreement.

PROVIDER ACCEPTANCE / EFFECTIVE DATE

CLIENT ACKNOWLEDGEMENT / DATE

Crown service: 24/7 automated monitoring where telemetry is supported; one included annual diagnostic review and owner walkthrough. Investigations are triggered by the documented age, weather or performance rules. Enrollment, access, response arrangements and any additional scope are confirmed with the selected firm.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

TECHNICAL / REPRODUCIBILITY

Source and calculation audit trail

Public sources, actual UI excerpts and editable scenario formulas

Historical imagery configuration

Esri Wayback release IDs, WMTS tile templates and corresponding source-metadata services.

County parcel boundary

Exact situs query retained; overlay is geographic context, not a survey.

RoofQuote PRO attempted flow

Observed address and roof outline retained; pricing/area/waste not issued before verification gate.

DOE / NREL performance methods

Measured/model energy, availability and performance ratios; proposed Crown alarm values are explicitly separate.

BNEF module tier methodology

Manufacturer bankability classification; not a module-quality certification.

SolarEdge warranty information

Public manufacturer search result states a standard 12-year inverter warranty; exact current product terms require serial-specific confirmation.

Evergy private-generation rates

Tariff-specific credits and time-of-use periods. The actual customer tariff remains to be confirmed.

Editable workbook

Inputs, settlement math, age sensitivities, quantity audit, monitoring trigger example and full imagery register accompany the PDF.

06 / ROOF AGE + INSURANCE FUNDING

The 10-15 year coverage cliff

A renewal-review window, not a universal age cutoff or a new claim deadline.

As roofs age, some insurers restrict replacement-cost eligibility or apply ACV or a roof-payment schedule. The 10-15 year range is a practical time to verify the policy in writing. The actual change depends on carrier, state, material, condition, endorsements and renewal terms. This roof's age and settlement terms are unknown.

RCV / Replacement cost	For an accepted covered scope, eligible replacement-cost benefits may include recoverable depreciation after the required work and documentation. The deductible and other applicable terms still apply.
ACV / Actual cash value	Typically replacement cost less depreciation. Under an ACV-only settlement, that depreciation is generally not recoverable, so owner funding can be much higher.
Not every ACV payment is final	An RCV policy may pay ACV initially, then release eligible depreciation after repairs. Confirm the actual endorsement, completion requirements and deadlines with the insurer. [S9-S11]

Illustration only: $20,000 covered replacement; $10,000 assumed depreciation; $5,000 deductible. This is not a quote or a finding for this roof.

Same accepted $20,000 scope	RCV scenario	ACV-only scenario
Initial net insurer payment	$5,000	$5,000
Eligible later depreciation	$10,000	$0
Final insurer / owner total	$15,000 / $5,000	$5,000 / $15,000

Ask the agent now: Is the roof settled at RCV, ACV or a schedule? Is depreciation recoverable? What is the wind/hail deductible? What changes at renewal? A condition report does not create coverage. Sources explain their own programs; this is not a statement of owner and co-owner's policy.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

07 / INSTALLER REFERRAL WORKFLOW

Protect the roof beneath the system.

A proposed contractor inspection handoff for solar installation and service teams

1 / INSTALLER INTRODUCES THE ROOFING REVIEW

Identify customers needing a roof baseline, leak/storm review or reroof. Explain Crown's scope and confirm the homeowner's interest and permission for contact, access and record sharing.

2 / HOMEOWNER SUPPLIES THE STARTING FILE

Collect roof history, symptoms/dates, claim papers, permits, solar plans, equipment schedule, monitoring and service/warranty contacts. Record what is received and what remains unavailable.

3 / CROWN INVESTIGATES AND REPORTS

Inspect accessible roof slopes, collateral, roof/PV interfaces and relevant attic/interior areas. Return documented observations, tests, supported causes, repairability, recommended scope, next steps and unresolved questions.

4 / INSTALLER RETAINS SOLAR SERVICE COORDINATION

Assign shutdown, diagnostics, warranty support, detach/reset and commissioning to qualified parties. Review written findings with the homeowner, then choose retail, financing or the claim path.

Suggested customer introduction: "We can connect you with Crown Roofing & Solar for a roofing and roof-to-solar interface review. With your permission, Justin will coordinate the inspection and return a written findings summary. Please share your roof history and any photos or concerns before the visit."

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

08 / FIELD PHOTO CHECKLIST — 1 OF 2

Roof condition + mounting hardware

Capture plan for the next visit | These items have not yet been certified as inspected.

ID	Photograph	Required context / detail
R01	Property + roof map	Address, all elevations and accessible roof slopes; north/orientation, slope IDs and array boundaries.
R02	Roof overview + controls	Wide and close views of exposed/sheltered comparison areas; material, layers where visible, wear and prior repairs.
R03	Marked conditions	Before marking, after marking and scaled close-up; shingle location, pattern and competing explanations.
R04	Repairability tests	With owner authorization: seal/access condition, brittleness and adjacent effects; sequence, controls and result.
R05	Collateral + flashings	Vents, gutters, soft metals, chimney, valleys, pipe boots and leak-related interfaces; overview and detail.
P01	Array + module inventory	Each array plane, row/column map and module count; photograph each accessible module and its location ID.
P02	Module identity + condition	Readable labels/model/serial/wattage where safely accessible; glass, frame, backsheet and visible defects.
P03	Rails + clamps	Rail profile, end/mid clamps, end caps, splices, offsets/overhangs and missing/loose-looking parts.
P04	Roof attachment + sealing	Feet, standoffs, flashing, boots and penetrations; corrosion, cracking, staining, fastener/seal interfaces.
P05	Wiring + bonding	Visible clips, cable routing, connector pairs, abrasion, unsupported loops, grounding/bonding and weather exposure.

Use original full-resolution files. Pair each detail with a wide locator view, scale where useful and the roof/array map. Do not lift modules, expose energized equipment or disturb attachments just to obtain a photograph; coordinate access with the solar technician.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

09 / FIELD PHOTO CHECKLIST — 2 OF 2

Equipment, operation + interior evidence

Record observed condition separately from tests or certifications by a qualified solar technician.

ID	Photograph / record	Required context / detail
P06	Inverter + electronics	Installed location, readable nameplate/model/serial and display/indicator state; optimizer or microinverter IDs if accessible.
P07	Electrical exterior record	AC/DC disconnects, combiner, meter, rapid-shutdown device, placards and visible ratings; closed covers unless qualified.
P08	Monitoring + baseline	App/portal identity, account access, capture date/time, alerts, module map, power and 12-24 months of kWh exports.
P09	Service + warranty	Installer stickers/contact, service tags, permits, approved plans, equipment schedule, PTO and warranty/service records.
I01	Attic + decking	Accessible underside below concern areas: staining, deck condition, penetrations, ventilation and moisture indicators.
I02	Interior symptoms	Room/location, wide and close views, homeowner timeline, visible staining; meter readings with location/method if taken.
T01	Test conditions	Who tested, qualification, method, instrument/settings, weather, shading, time, controls and limitations.
D01	Before detach / storage	Serial-position map, handling condition, labeled parts, protection and chain of custody if work is later authorized.
D02	After reinstall	Attachment/flashing close-ups, accessible connection/bonding record, technician commissioning results and exceptions.
D03	Production comparison	Post-work monitoring, dates/downtime and normalized pre/post production; faults routed through installer/manufacturer process.

Qualified technician scope: electrical isolation, opened enclosures, connection/torque checks and electrical commissioning. Crown documents accessible construction conditions and coordinates specialists. No electrical performance test is represented as completed in this report.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

10 / STORM EXPOSURE

The August 19 exposure window

Regional NWS reports cited by the source report; not independently reissued in this revision.

NORTH KANSAS CITY AREA


Reported hail: 1.25 inches at 1 NW, 1.50 inches at 1 SSE and 1.75 inches at 2 SE. These reports anchor a regional event window; they do not measure hail size at this parcel or establish roof damage. [S1-S2]



7-Aug 24, 2026 18-00-48-oTc2.jpg



38-Aug 24, 2026 18-10-14-X4YS.jpg



40-Aug 24, 2026 18-11-19-PEtL.jpg



55-Aug 24, 2026 18-16-05-eG1G.jpg

Construction correlation. Marked shingles and collateral metals warrant evaluation alongside physical characteristics, direction, weathering, complete photos and field notes. Functional damage and causation require property-specific findings.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

11 / ROOF SYSTEM

Document the roof as one system



49-Aug 24, 2026 18-15-50-tCZv.jpg



62-Aug 24, 2026 18-18-25-Lh4H.jpg



76-Aug 24, 2026 18-25-26-R5Qp.jpg



85-Aug 24, 2026 18-28-11-gkVL.jpg

OBSERVED / DOCUMENTED

Architectural asphalt shingles; roof penetrations and chimney flashing; roof-mounted PV arrays; chalk-marked evaluation locations; localized debris/vegetation; and aged interfaces. Existing observations do not replace a final repairability determination.

Scope recommendation from the inspection report: develop a full replacement scope coordinating roofing, flashings, ventilation, PV attachments, electrical shutdown, storage, remounting, commissioning and evidence preservation.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

12 / INSPECTION EVIDENCE

Marked shingle conditions

Selected original inspection photographs | Image content preserved



106-Aug 24, 2026 18-30-37-w6A5.jpg



107-Aug 24, 2026 18-30-55-vpLj.jpg



112-Aug 24, 2026 18-30-47-zewj.jpg



118-Aug 24, 2026 18-30-29-Yknw.jpg



167-Aug 24, 2026 18-33-04-VxZV.jpg



180-Aug 24, 2026 18-34-51-CdXg.jpg

Chalk marks identify evaluation locations. Read these selections with the complete inspection archive and field notes; a marked surface alone does not establish functional damage, cause or coverage.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

13 / REPAIRABILITY

Test before choosing the repair scope



79-Aug 24, 2026 18-26-58-tqxE.jpg



80-Aug 24, 2026 18-27-00-mE4c.jpg


81-Aug 24, 2026 18-27-04-dFGH.jpg



83-Aug 24, 2026 18-27-07-oVUk.jpg



110-Aug 24, 2026 18-30-13-TaAy.jpg



115-Aug 24, 2026 18-30-28-SXqe.jpg

Reporting limit. Assess actual seal condition, fastener access, brittleness, adjacent damage risk, material matching and manufacturer requirements. Record the test method, control areas and observed results before finalizing scope.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN


SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK


FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

14 / COLLATERAL + INTERFACES


Connect the details to the scope



17-Aug 24, 2026 18-02-01-4D3t.jpg



18-Aug 24, 2026 18-02-34-nkXz.jpg



19-Aug 24, 2026 18-02-35-uPXQ.jpg



93-Aug 24, 2026 18-29-08-P1Ly.jpg



99-Aug 24, 2026 18-29-18-Dm3K.jpg



103-Aug 24, 2026 18-29-21-YdGC.jpg

Scope coordination. Inventory pipe flashings, roof vents, chimney details, PV attachments, gutters and other collateral components before work. Tie replacement decisions to physical condition, adopted code, manufacturer instructions and the written construction scope.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

15 / CONDITION + CAUSATION ANALYSIS

What the available record supports

Preliminary contractor desk review | Field investigation and specialist diagnostics remain open

Recorded condition	Selected August 24 photographs document architectural shingles, PV arrays, marked evaluation locations and roof/collateral interfaces. Marks locate observations; they do not establish functional damage or a loss date.
Storm hypothesis	Regional August 19 hail reports justify investigation. To support a storm-related cause, document material fracture/deformation, distribution, directional/collateral consistency, symptom timing and alternatives. No parcel-specific hail measurement is supplied.
Wear / prior condition	Age is unverified. Evaluate ordinary weathering, blistering, prior repairs and material/installation condition using unmarked controls and history. Do not infer age or causation from appearance alone.
Mechanical / solar interface	Compare tool/foot-traffic patterns, handling marks, penetrations, attachment flashing and leak paths. Any association with solar work must be supported by records and physical evidence, not proximity to the array.
Repairability + scope	Test proposed access and repair methods, available matching materials, seal/brittleness response and connected components. A replacement scope needs a documented construction basis.
PV performance	No current baseline, inverter identity, fault log or commissioning test is available. Electrical malfunction, production loss and warranty remedy cannot be determined from panel appearance.

WRITTEN NEXT-STEP RECOMMENDATION

Complete the field photo/test plan, reconcile roof age and prior repairs, obtain monitoring/service records, and compare competing causes. The final contractor analysis should identify the observed condition, supported mechanism, confidence and limits, repair options, proposed scope and any specialist referral.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

16 / CONDITIONAL CLAIM-READINESS SCENARIOS

Readiness follows the evidence.

Likelihood of a supportable construction submission remains indeterminate before the field review.

SCENARIO A / STRONGER SUPPORT AFTER CORROBORATION

Consistent chronology, property-specific damage, matching collateral and documented repairability strengthen the construction basis for submission. The homeowner reports supported facts and provides the claim number; Crown prepares the technical record.

SCENARIO B / MIXED OR INCOMPLETE EVIDENCE

If aging, prior repairs, installation or mechanical effects remain plausible, or records conflict, readiness is unresolved. Obtain missing history, controls, tests and specialist input before a firm conclusion.

SCENARIO C / NO SUPPORTED STORM-RELATED CONDITION

Wear, maintenance or isolated defects without a corroborated storm mechanism weaken a storm-loss theory. Record the findings and price appropriate retail repairs, roof/PV work or installer/manufacturer service.

Current file: 50/100 measures evidence completeness. Roof age, claim history, field tests, baseline and service responsibility remain unresolved. A numerical claim-approval probability is not supportable.

CONTRACTOR ROLE + FINAL WRITTEN ASSESSMENT

Crown provides observations, measurements, construction/repairability analysis, estimates and guidance within documented qualifications. Insurers decide coverage/payment. The final reviewer identifies their name, expertise, investigation date, evidence, reasoning, limits and next action. Field expert sign-off remains pending.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

17 / SOLAR SYSTEM

Identify the equipment. Capture the baseline.

Documented	Roof-mounted PV across multiple roof planes. City permit identifies SUN SOLAR LLC. The fuller source report transcribes module frame serial Q52205200303130115930588; that original label image was not independently examined in this revision. [S2-S3]
Pending identification	Module manufacturer/model, wattage and count; inverter manufacturer/model/serial; DC/AC ratings; string, optimizer or microinverter architecture; racking and attachments.
Monitoring record	Open the existing app, confirm account ownership, export 12-24 months of production and alerts, and capture module-level data where available.
Warranty record	Obtain original contracts, serial-specific warranty start/expiry, purchased extensions, transfer terms and any installer service agreement. A 2020 installation does not establish equipment brand or current warranty eligibility.

COMPARE CORRECTLY

Normalize pre/post production for irradiance, weather, season, shading, downtime and known faults. A generic production-drop percentage alone is not a defect diagnosis. Use fault codes, tests and the manufacturer's process.

18 / CONTROLLED WORK SEQUENCE

Detach. Protect. Recommission.

01 / BEFORE REMOVAL

Obtain portal access and equipment schedule. Record status, alerts and production. Photograph every module and serial/position. Map roof attachments and electrical labels. Establish the shutdown and chain-of-custody plan.

02 / DURING ROOFING

Use qualified shutdown and isolation. Label modules, rails, wiring and hardware. Inspect connectors, backsheets, glass and frames. Store securely and separate damaged components. Install roofing and flashed attachments to written requirements.

03 / AFTER REINSTALLATION

Verify torque, connections, grounding and bonding. Commission inverter and communications. Confirm module-level visibility where supported. Compare weather-normalized production. Record exceptions and follow manufacturer claim procedures.

Performance standard: investigate any material departure from the documented baseline after accounting for operating conditions. Manufacturer warranty terms and diagnostic procedures govern eligibility.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

19 / OWNER CHOICES

Choose the scope after diagnostics

LIKE-FOR-LIKE DETACH + RESET

Preserve the existing architecture when equipment passes diagnostics. Document the baseline, renew compatible mounting/flashing and recommission.

STRING-INVERTER REFRESH

If a confirmed string inverter fails diagnostics or warrants replacement, price a manufacturer-approved solution and verify compatibility with optimizers and modules.

MICROINVERTER CONVERSION

An optional owner election requiring compatibility, code, communications, warranty and cost review. Confirm the existing architecture first.

ROOF-SYSTEM UPGRADE

Evaluate impact-resistant shingles, ventilation corrections, accessories and attachment/flashing details against the final scope and homeowner priorities.

Insurance / warranty: Crown documents conditions, estimates and technical work. Coverage and payment decisions remain with the homeowner and insurer; product-warranty decisions follow the manufacturer/EPC terms. No upgrade is represented as automatically covered.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

20 / NEXT STEPS

Close the gaps in the property file

Work item	Suggested owner	Required record
1 / Installer service	Homeowner + installer	Obtain dated written service/warranty acceptance, support case and monitoring access.
2 / Equipment record	Qualified solar technician	Photograph nameplates; list modules, inverter, architecture, racking and serials.
3 / Roof repairability	Crown field reviewer	Document seal/brittleness tests, collateral findings, causation and final scope.
4 / Claim history	Homeowner	Supply insurer, claim number, prior filings/decisions, carrier scope and correspondence.
5 / Baseline + sign-off	Solar technician + Crown	Export production/alerts; document pre-removal state; record final commissioning results.

READINESS REVIEW

Rescore only when evidence is added. Document the reviewer's name, review date and supporting file references. The score is provisional and has not been signed off by a field reviewer.

Open meeting items: ownership/financing/lease/PPA; purchased warranty extensions; active alerts; desired owner-paid upgrades; and installation/repair records.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

21 / EVIDENCE + REFERENCES

A traceable record, with clear limits

S1 / Source inspection example

12-page Kansas City Solar Current Condition Report Example; 26 selected inspection photos and attached excerpts.

S2 / Fuller owner report transcript

Adds property/permit profile, equipment questions and evidence manifest. Archive named gallery-ahxEn9NQ-photos-1787609181.zip; 274 originals reported, not downloaded here.

S3 / Official property permit

Exact address and permit match; issued/closed dates, contractor and reported cost retrieved Nov 11, 2026.

S4 / KCMO permit dataset

Exact contractor-name query: SUN SOLAR LLC. 139 records; issue range Aug 6, 2020-Mar 5, 2025. Metadata last updated May 9, 2025.

S5 / Installer contact page

Current public service and main phone numbers, Kansas City service area statement. Retrieved Nov 11, 2026.

S6 / BBB business identity

Business-name aliases and matching Springfield contact details; no state good-standing certificate reviewed.

S7 / Installer service description

Company advertises servicing; page dated July 18, 2024. Not proof of an active owner service agreement.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

22 / ROOF-AGE + FUNDING SOURCES

Sources for the added investigation plan

S8 / Second official permit dataset

Exact-address query: [property address withheld]; parcel [ID withheld]. Returned the 2020 solar permit, a voided 2020 electrical record and the 1989 plumbing record. No roof-replacement record was returned. Retrieved Nov 11, 2026.

S9 / Farm Bureau Financial Services

Its own comparison discusses 10-15-year treatment and differing RCV/ACV schedules. Its stated RCV availability and loyalty provisions have conditions; they do not establish this homeowner's policy.

S10 / American Family Insurance

Explains ACV roof settlement and optional RCV eligibility based on age/type. Availability and policy terms vary by state.

S11 / Travelers depreciation guide

Explains depreciation, initial ACV payments and potential recoverable depreciation under replacement-cost coverage; condition and policy requirements matter.

S12 / Crown evidence, estimates and financing

Crown's working public intake, instant-estimate and financing pages supply the closing-page destinations. Financing decisions remain with the provider.

S13 / Crown project protection review

Current public page distinguishes supplied comparison materials from live Directorii terms. Confirm the applicable program, limits and registration in writing.

Research date: November 11, 2026. Permit absence does not prove the roof was never replaced. No new onsite visit, destructive test, electrical test or carrier coverage review was completed for this revision.

23 / EVIDENCE INTAKE

Before we finish: complete your evidence file.

Homeowner | Send the records you have not yet shared with Crown.

What happened + when	Your own timeline, first symptoms, leaks, temporary repairs and any uncertain dates.
Original photographs + video	Before/after images, roof/interior views and storm footage. Keep full-resolution originals and capture dates.
Roof + repair history	Installation invoices, old inspections, repair receipts, product labels and warranty documents.
Solar + installer records	Sun Solar contract, equipment labels, monitoring exports, service history and warranty correspondence.
Any existing claim file	Insurer, claim number, carrier estimate, decisions, inspections and correspondence, including earlier claims.
Costs + changes	Mitigation receipts and dated records of work or changes since the loss. Mark anything you still need to locate.

SEND YOUR EVIDENCE NOW

Email reports@crownroofingict.com
Use "[property address withheld]" in the subject. Attach the records in your email app; request a transfer link for large files.

Already presenting in person? Share the files now. Justin can record what is received, what is still missing and who will supply it. Keep original files; do not send banking credentials or unrelated ID documents.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

24 / RETAIL + FINANCING

Get the numbers. Choose the right package.

Start with the instant estimate. Then ask Justin for itemized, written retail prices.

GOOD

A complete roofing scope with compatible solar detach/reset and documented recommissioning where required.

BETTER

Compare an upgraded or impact-resistant roof system, improved ventilation and renewed roof/PV interface details.

BEST

Compare premium roof-system choices and any justified solar equipment, monitoring or system improvements.

ROOF + SOLAR COMBINATION

Request one written price for the roof package, solar detach/reset, attachments/flashing, diagnostics, commissioning and selected solar upgrades. Confirm compatibility and installer/warranty responsibilities.

FINANCING: PREQUALIFICATION > PREAPPROVAL

Choose a provider and apply for prequalification, then obtain written lender preapproval or a credit decision. Compare APR, fees, monthly payment, total repayment and any property lien. Prequalification is not final approval or funding.

Before choosing: receive the hard retail numbers for Good, Better, Best and the roof + solar combination. Compare the same measurements, tear-off, decking allowances, flashing, ventilation, PV work, exclusions and warranties. No property-specific retail price has been supplied in this report.

Justin confirms Kansas City availability, the complete scope and final written retail price.

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK

25 / YOUR DECISION + SIGN-OFF

Your decision and sign-off.

REQUIRED: choose one roofing path and one solar provider. Save the PDF and attach it before emailing.

HOMEOWNER / AUTHORIZED OWNER *

HOMEOWNER EMAIL *

1 / HOW ARE YOU COMPLETING THIS REPORT? *

- ◯ With a Crown representative
- ◯ Remotely and independently REMOTE ONLY: BOOK REVIEW >

REMOTE ONLY: BOOKED REVIEW DATE / CONFIRMATION *

2 / ROOFING DECISION - SELECT ONE *

- ◯ Retail: instant planning estimate
- ◯ Retail: firm written quote
- ◯ Insurance: claim / evidence-file preparation
- ☐ Retail only: financing prequalification (separate lender consent).
- ◯ Existing claim
- ◯ Agree to next-step review before filing / work order

EXISTING CLAIM: INSURER / ACTUAL CLAIM NUMBER *

WITH-REP INSURANCE: SIGNED WORK-ORDER REF. / DATE *

☐ Signed work order confirmed (with-rep insurance).

With-rep insurance: actual claim number and signed work order are required.

3 / SOLAR SERVICE - SELECT ORIGIN + PROVIDER *

- ◯ Direct client / no active-servicing partner referral
- ◯ Referred by partner currently servicing solar

ONGOING SOLAR PROVIDER - SELECT ONE *

- ◯ Retain original provider
- ◯ Retain referring partner
- ◯ Choose eligible Crown service

ACTIVE-SERVICING PARTNER REFERRAL = CROWN ROOFING ONLY; Crown solar unavailable.

ONGOING SOLAR FIRM / SERVICE CONTACT *

AGREEMENT REFERENCE / SERVICE START DATE

REFERRING PARTNER, IF APPLICABLE

CROWN ENROLLMENT ONLY: PRICE / BILLING FREQUENCY

Remote only: book review and agree to the next step if claim / work order is pending. A booking does not file a claim or start solar service.

☐ I authorize the selected next step; scope and any charge must be agreed in writing. *

☐ I reviewed pages 19-23 and 38-43: provider roles, triggers, exclusions and evidence obligations. *

OWNER TYPED SIGNATURE * - INTENT TO APPROVE SELECTED NEXT STEP

ACTUAL SIGNING DATE *

CROWN EXPERT NAME / SIGN-OFF (CROWN COMPLETES)

SOLAR FIRM / REP. ACCEPTANCE (PROVIDER COMPLETES)

EMAIL COMPLETED REPORT | ATTACH / EMAIL EVIDENCE | REQUEST WORK ORDER

EVIDENCE FIRST | CHOOSE YOUR NEXT STEP WITH JUSTIN

SEND YOUR EVIDENCE
Records + original photos
SCAN OR CLICK

INSTANT ESTIMATE
Start with your address
SCAN OR CLICK

FINANCING OPTIONS
Prequalify with a provider
SCAN OR CLICK